CREW: 162	WORK ORDER TYPE: MODIF	ICATIONS			01-19846-9	ISSUE DATE 01/06/11	Pa	ge 1 Of 2			
Originator	: KEVIN MILLER	Schedule Date	:			Date Completed:		Failure Code:			
Planner	: KEVIN MILLER	Priority	: 3C								
Drawing No	: 2TGA-M2079	Clearance	: NO			Completed By :		Signature :			
Equip No/Ca	at: 2TGA1 1	Tag Request	:								
Project ID		Text ID	:			Accepted By :		Signature :			
Shutdown	: U Unit	Frequency	: NO'	r sc	HEDULED			_			
Ref No	:	Last Reading	: No	Rea	ding			** Delay Co	des Legend **		
		J			•		W=Whse	C=CrSp T=	Tag TL=Tool	P=Plan	
							** F	Record Time Da	ily **	Delays	
Step Job	Scope		MN I	DΥ	Safety and Additional	l Information	Emp No	Date	Hours	Code/Hrs	
					<del>-</del>						
1 PUL	L TWO NEW THERMOCOUPLE CA	BLES REQUIRED	2	1	******	*****					
	BY ALSTOM FOR THE NEW HIGH PRESSURE				SAFETY / ENVIRONMENTA						
	BINE.				A. ALWAYS WEAR THE	_					
1010						*					
***	*****	*****			B. NO WORK CARD REC	QUIRED. TERMINATIONS					
JOB	SCOPE:				WILL BE BY OTHERS.	(01112) 121111111111111					
	. AT THE TIME OF THIS WRI	TING THE									
	CT SCOPE OF WORK IS NOT K	•			C. TIE OFF WHEN WOR	RKING IN THE CARLE			<del></del>		
	TERMINATIONS. WE DO KNO				TRAY AREA.						
	ITIONAL THERMCOUPLES ARE				11011 1110111						
	ORE ALSTOM WILL WARRANTY				*******	******					
	TURBINE.				ADDITIONAL INFORMATIO	M·					
1010	BINE.				A. OBTAIN 1000' OF						
າ	. PLEASE CONTACT KEVIN MI	מחד. ב מחש מתוו			EXTENSION CABLE STAGE						
	KDOWN.	DDER FOR A GOD			ALONG WITH A J-BOX AN			· · · · · · · · · · · · · · · · · · ·			
WALL	IKDOWN:				ADONG WITH A C DOX AL	ND JO OF I FIFE.					
2	. INSTALL J-BOX ON THE NO	PTH SINE OF									
	HIGH PRESSUR HOOD AS DIS										
	LD WALKDOWN. INSTALL CON										
	REST TRAY.	DOIL PROM									
WEA.	RESI IRAI.										
1	. TWO CABLES NEED TO BE P	ייי איי מייי מייי מייי									
	LD I/O CABINET (FOX) AND										
	L BE TERMINATED ON THE TO										
	LL OF THE NEW TURBINE. P										
	LE AS YOU WISH BUT TRY TO						***************************************				
	CTRONICS (SIGNAL) LEVEL C										
	CH ARE LABELED 2TEC0023 F										
	'E' SIGNIFYING ELECTRONI										
INE	L SIGNIFIING EDECIRONI						J.	r* TMD/(Dመአነጥ ነ፣	OTTOR **		
-	DIENCE WDITE DOWN THE D	ለተምሮ <b>ህ</b> ላተ ሞልሂቱ						* IMPORTANT N SPONSIBLE FOR		W AND MILOT	
	5. PLEASE WRITE DOWN THE ROUTE YOU TAKE AND RETURN WITH THE WORK ORDER SO I CAN										
	ER THE CIRCUITS IN THE PR							THE REQUIRED			
	ABASE.	OUECI					JOB YOU ARE DOING. IF YOU HAVE ANY QUESTIONS CONCERNING THE WORK RULES, SAFETY CODES, OR				
DAT	ADADE.										
								PE, PLEASE CON			
	.1 /**					*					

Job Feedback/Historical Notes:



	**	Work	Order	Parts	List	**
Part No	Description					

Part No		Description	PO/Req/SIR	Date Due	U/M	Reqd	Commit	Issued/Rcvd	
1	19933	BOX, JUNCTION	S 206326	03/06/02	EA	1	0	1	
2	50618	ROD, ALLTHREAD	S 209570	03/21/02	EA	1	0	1	
3	58168	CONDUIT, FLEXIBLE	S 209332	03/20/02	FT	10	. 0	10	
4	58394	CONDUIT, RIGID	S 209327	03/20/02	PC	7	0	7	
5	58396	CONDUIT, RIGID	S 206326	03/06/02	PC	0	0	0	
6	66161	CABLE, THERMOCOUPLE	S 206326	03/06/02	FT	1000	0	1000	